4 1:-

ENVIRONMENTAL CLEANUP SITE INFORMATION SITE SUMMARY REPORT

21, 2000 03:04 pm April

SITE NAME: Oregon Steel Mills - Rivergate CERC IS NO: 009106055

> ALIASES: Gilmore Steel Corp. - Rivergate

Portland Harbor Site Discovery

ADDRESS: 14400 N Rivergate BLVD Portland 97203

COUNTY: REGION: NWR MULTNOMAH

INVG STATUS: SUS NPL SITE: N ORPHAN SITE: N STUDY AREA: N --**--**---

TWNSHP/RANGE/SECT: 2N, 1W, 26 PROPERTY. TAX LOTS: 1 of Lot 1 (R64977 4290)

LATITUDE: 45 deg.37'18" LONGITUDE: 122 deg.46'49" SITE SIZE: 158 acres

STUDY AREAS: STUDY STUDY INVG ID STATUS

> 1544 Lower Willamette River Basin Study Area (LWRBSA) XCN

XCN 2339 V.A. - Designated National Estuaries

2340 V.A. - Surface Waters, WQ-Limited for Toxics XCN

XCN 2068 Portland Harbor Sediments

NAME: Oregon Steel Mills - Rivergate

COMMNETS: Steel rolling and finishing mill

YEARS OF OPERATION:

OPERATING STATUS: Active SIC CODES: 3312

Site ID : 141 Oregon Steel Mills - Rivergate SITE SUMMARY REPORT

PE' 1TTS: - A----

PERMIT NO: PERMIT TYPE

ISSUED BY COMMENTS

100170 NPDES 26-1865 ACDP

DEO/WO DEO/AO

1207 WO GEN12H

DEO

HAZARDOUS SUBSTANCES/WASTE TYPES:

lead, cadmium, chromium, PCB

- MANNER AND TIME OF RELEASE:

Operating practices.

Time of release: Unknown

CONTAMINATION INFORMATION:

Company: (1) solvent mixed with paint leaked from drums onto the surface of the ground; (2) landfilled large volumes of waste paint on site; (3) deposited emission control dust (determined to be characteristic hazardous waste) into a surface impoundment not intended for that purpose; and (4) experienced at least 2 PCB spills from leaking capacitors and transformers.

SUBSTANCE CONTAMINATION _____

OBSERV. ATCHM CONTAMINATED CONCENTRATION LEVEL EVIDENCE DATE SUBSTANCE _____

Soil 27.64 ppm Sediment 1.35 ppm CADMIUM

Landfill Closed

Date released: Unknown Quantity Released: Unknown Data Source: NWR Source files

CHROMIUM

1,532 ppm Soil

Landfill Closed

Date released: Unknown Quantity Released: Unknown Data Source: NWR Source files

LEAD

1.3

553 ppm 101 ppm Soil Sediment

Landfill

Closed

Date released: Unknown

Laboratory Data 01JUN1997

Laboratory Data 01JUN1997

Site ID: 141 Oregon Steel Mills - Rivergate SITE SUMMARY REPORT Page 3

Quantity Released: Unknown Data Source: NWR Source files

PCB 1221

Soil 7.9 ppm
Date released: Unknown
Quantity Released: Unknown
Data Source: NWR Source files

PCBs

Sediment

1,971 ppb

Laboratory Data 01JUN1997

ZINC

Sediment

474 ppm

Laboratory Data

01JUN1997

STATUS OF INVESTIGATIVE OR REMEDIAL ACTION:

Company: (1) cleaned up a portion of the landfilled paint wastes; (2) cleaned up the PCB-contaminated soil; (3) removed the contaminated emission control dust from the surface impoundment. (8/5/99 TG/SAP) Strategy Recommendation for high priority Remedial Investigation to evaluate sediment contamination. (3/1/00 JMW/SAP) Voluntary Agreement for Remedial Investigation and Source Control Measures forwarded to Oregon Steel Mills, Inc. on February 29, 2000. Signed agreement due March 31, 2000.

INVESTIGATIVE, REMEDIAL, AND ADMINISTRATIVE ACTIONS

ACTION te added to database	START DATE 16AUG1988	COMPL. DATE	RESP. STAFF John Odisio	AGENCY CODE DEO	REGION	LEAD PROGRAM SAS
Responsible party notified re	30NOV1988			DEQ		SAS
SITE EVALUATION	27FEB1990	27FEB1990	John Odisio	DEQ	HQ	SAS
State Basic Preliminary Assessment recommended (PA)	27FEB1990	27FEB1990	John Odisio	DEQ	HQ	SAS
*BASIC PRELIMINARY ASSESSEMENT COMMENTS: Federal.	28FEB1990	28FEB1990	John Odisio	DEQ		SAS

Site I	D: 141	Oregon S	Steel Mills	- Rivergate	SITE SUMMAR	Y REPORT		Page 4	
,			,						
Site added to CERC	LIS	. 	17SEP1991			ЕРА			
EPA Basic Prelimin COMMENTS:	ary Asses Site de	ssment eferred to	03SEP1992 EPA Regio	03SEP1992 n 10's RCRA	unit.	EPA			
SITE EVALUATION			05AUG1999	05AUG1999	Thomas Gainer	DEQ		SAS	
Remedial Investiga	tion reco	mmended	05AUG1999	05AUG1999	Thomas Gainer	DEQ	NW	SAS	
Priority for Further Action: HIGH COMMENTS: Strategy Recommendation - High priority for an RI.									
LAST UPDATED BY: j	mw	DATE:	21-APR-00			=======================================			

	Site II): 141	Oregon	Steel Mil	ls - Rivergate	SITE	SUMMARY			Page	5
4				.=======	=========		======		======	========	
Proposal List rec	ommended				9 010CT1999 lated gw conta		Gainer	DE	Q NW	SAS	
• • • • • • • •											
	COMMENTS:	Gasolin	e spill	and assoc:	9 010CT1999 iated gw conta	amination.					
Facility Release	proposed : List	for Confi	rmed		9 12NOV1999		n Patten	DE	WИ Q	SAS	
	• • • • • • • • • • • • • • • • • • • •					• • • • • • • • • • • • • • • • • • • •	• • • • • • •		• • • • • • • •		
ility	proposed :	for Inven	tory	12NOV199	9 12NOV1999	Kim Van		DE			
						• • • • • • • • • • •		• • • • • • • • • •			
owner/op					9 15DEC1999				Q NW		
										• • • • • • • • • • • • • • • • • • • •	
	COMMENTS:	Extensi	on grant	ted to Febr	9 27DEC1999 ruary 18, 2000).			Q NW		
• • • • • • • • •			• • • • • • •		<i></i>		• • • • • • •			• • • • • • • • •	
Owner/op on listi	ng notifica	ation			0 17FEB2000 r.Proposed lis						
	greement COMMENTS:	Volunta	ry Agree	ement for 1	0 RI and Scope o	of Work.		DE	~		
• • • • • • • •									• • • • • • • •	• • • • • • • • •	
NEGOTIAT	'IONS			29FEB200	0	Rod Str				VCS	
			• • • • • • •								
	=======================================	========	======				======	=======	=======	=======	=
13					ACTIVE PROJE	ECTS					
PROJECT			PROJI	ECT							
ID			IAN	ME							
7880	Oregon St	eel Mills									
COMMENT:											
======	:=======	======	======	========	DADTV TNEODM		======	#=======	======	=======	=====
SITE CON	ITACT:				PARTY INFORM						
Drew Gil	pın										

```
Site ID : 141 Oregon Steel Mills - Rivergate SITE SUMMARY REPORT
Mgr Environ Svcs - Portland Steelworks
Oregon Steel Mills Inc
PO Box 2760
Portland , OR 97208
PHONE: (503) 978-6189
ASSOCIATED PARTIES
                                                                INFORMATION
NAME AND ADDRESS
                          AFFILIATION
                                                 AFFILIATION STATUS
                                                               AS OF DATE
Oregon Steel Mills
                          Unknown
                                                                16AUG1988
Division of Gilmore Steel
14400 Rivergate Boulevard
Partland , OR 97203
 MMENTS:
......
                         Legal Owner
Drew Gilpin
                                                                10FEB2000
Mgr Environ Svcs - Portland
Steelworks
Oregon Steel Mills Inc
PO Box 2760
14141 N Rivergate Blvd 97203
Portland , OR 97208
(503) 978-6189(FAX (503) 240-5237)
OSM acquired the property in 1961 from the Port of Portland.
Kevin Ratliff
                          Owner
                                                                22DEC1998
Plant Manager
Oregon Steel Mills, Inc
PO Box 2760 (97208)
14400 N Rivergate Blvd (97203)
Portland , OR 97203
(503) 286-9651((503) 240-5777)
COMMENTS:
         OWNERSHIP COMMENTS:
DATA SOURCES:
                     1) NRW HW file
                     2) NWR AQ file
                     3) NWR WQ file
                     4) "Contractual Documentation for Part A Application" (12/19/91)
                     Inspection reports
                     Correspondence FROM owner and/or operator
                     Notice of Violation Letter
                     Hazardous Waste Manifests
                     Lab results
( site report.rpt )
```